

Title: <b>Inverter and Compressor Update</b>	
Creation Date: September 7, 2021	Service Pointer Number: <b>HRF-07-09-22</b>
Revision Date: November 14, 2022	Models: See Table Below
Symptom: poor cooling, no cooling	

## Issue:

There has been an update to the compressor & inverter board on newer HRF266/HRF254 units. Please check the serial number to ensure the correct parts are ordered. See the chart below for the serial number range and new part numbers.

If the serial code falls **AFTER** the chart below you will need the new part number(s) listed below for the part(s) you may need.

If the serial number falls **BEFORE** the dates listed below you will need to order the **ORIGINAL** part number(s) from the parts breakdown.

## Serial Number Range:

See chart below for model information and serial date range. Also listed below is an example serial code and how to decipher a Hisense refrigerator serial date code.

MODEL NUMBER	SERIAL NUMBER RANGE	PART NUMBERS
HRF266xxxxx	All production <b>AFTER</b> C20210810xxxxx	K2203959 (Compressor) & K2212650 (Inverter)
HRF254xxxxx	All production <b>AFTER</b> C20210812xxxxx	K2204942 (Compressor) & K2204803 (Inverter)



C
YYYY
MM
DD
00001


Line
Year
Month
Day
Production Number

## Repair: See Steps Below

Original Board Location



HRF266 New Board Location



HRF254 Board Location

